

Genie Used Equipment Listing Details

2013 GENIE GS-2632 2WD DC Scissor Lift

USD 7,095.00

Unit Specifications

| TMS ID | 1049905*UEQ |
|----------------|--|
| Year | 2013 |
| Make | GENIE |
| Model | GS-2632 |
| Serial Number | GS3213A-112817 |
| Equipment Type | Scissor Lift |
| Drive | 2WD |
| Power | DC |
| Height | 26 |
| Engine Make | |
| Engine Model | |
| Hours | 174.9 |
| Location | ACCESS LIFT EQUIPMENT, INC CHAMBERSBURG Pennsylvania |

Contact Information

Genie Used Equipment 1 (800) 800-1290 <u>AWP.GenieUsedEquip@terex.com</u>

All sales of used equipment by Genie are subject to Genie's standard terms and conditions of sale of used equipment. Used equipment shown on this web site or otherwise sold by Genie is sold as-is, where is, with all faults, and Genie makes no warranties of any kind, express or implied, with respect to it.

Inspection Report

As the buyer, you are responsible for reviewing all details of the inspection report.

Star Ratings

| **** | Limited use or recently replaced. Free of visible wear or defects. |
|--------------|---|
| ★★★ ☆ | Performs within the tolerances expected for age and type of unit. |
| ★★ ☆☆ | Although performing, shows indication of needing repair or replacement. |
| ★☆☆☆ | Needs immediate repair or replacement to function as expected. |

| Description | Details / Rating | Comments |
|---|---------------------|----------|
| On a scale 1-4, how would you rate the overall condition of this equipment? | ★★★ ☆ | |
| Inspect paint condition (fading, flaking paint, customer colours) | *** | |
| Inspect machine for any damage (Covers, panels, controls etc) | *** | |
| Inspect decals condition (Identify missing or damaged) | ***û | |
| Inspect for significant oils leaks and identify source | *** | |
| Does the machine have any options (Generator etc) | NO | |
| Inspect operators and safety & responsibility manuals are in place | YES | |
| All open bulletins addressed | YES | |
| Inspect tires and wheel for damage and wear | ***¤ | |
| Inspect axles for corrosion, damage or missing parts | *** | |
| Inspect chassis for corrosion, damage or missing parts | *** | |
| Inspect turntable or chassis covers for corrosion, damage or missing parts | *** | |
| Inspect link stack for corrosion, damage or missing parts | *** | |
| Inspect boom assembly for corrosion, damage or missing parts | N/A | |
| Inspect jib assembly for corrosion, damage and missing parts | N/A | |
| Inspect platform assemblies for corrosion, | ★★★ ☆ | |

| domodo | 0r | miccina | norte |
|--------|-----|------------|-------|
| damage | UI. | 1111551110 | Dalla |
| | | | |

Perform function test from ground controls with 'Safe Work Load (Max/Min)' in platform

Are the batteries charged?

YES

Are the batteries holding a charge?

YES

Would the equipment pass an annual inspection as per manufacturer's maintenance manuals?

4x Corner Shots (tires visible)



Engine Tray/Battery Pack



Fully Extended Equipment

Ground/Cabin Controls

Platform Controls

Platform/Carriage & Forks

Serial Plate











Photos







